



*Solving environment-related business problems worldwide*

[www.deltaenv.com](http://www.deltaenv.com)

27141 Aliso Creek Road • Suite 270  
Aliso Viejo, California 92656 USA

949.362.3077 800.477.7411  
Fax 949.362.0290

July 14, 2005

Mr. Sam Stevens  
Los Angeles County Department of  
Public Works  
900 South Fremont Avenue  
Alhambra, California 91803

Sent by UPS

Subject: Quarterly Update Report Submittal

Dear Mr. Stevens:

On behalf of Atlantic Richfield Company, Delta Environmental Consultants, Inc. is submitting the enclosed Quarterly Site Status Report for the Second Quarter 2005. The enclosed quarterly report was prepared for the following ARCO Facility:

**ARCO Facility No.**

1592

**LADPW Site No.**

EP-1 011979-037116

**Location**

5 West Foothill Blvd, Arcadia

If you have any questions, please contact the undersigned at (949) 360-5789.

Sincerely,

**DELTA ENVIRONMENTAL CONSULTANTS, INC.**

A handwritten signature in black ink, appearing to read "Amy R. Mora".

Amy R. Mora  
Project Manager

Enclosure: Atlantic Richfield Company Quarterly Site Status Report

cc: Mr. Darrell Fah, Atlantic Richfield Company, La Palma, California  
Mr. John Nahas, 5 West Foothill Boulevard, Arcadia, California

**ATLANTIC RICHFIELD COMPANY QUARTERLY SITE STATUS REPORT  
SECOND QUARTER 2005  
JULY 15, 2005**

ARCO Facility No.: 1592 Address: 5 West Foothill Boulevard, Arcadia, California  
Atlantic Richfield Co. Env. Manager / Phone No.: Darrell Fah / (714) 378-5105  
Consulting Co. / Contact Person / Phone No.: Delta Environmental / Amy Mora / (949) 360-5789  
Primary Agency / Contact Person / Regulatory ID No.: County of Los Angeles Department of Public works (LADPW) /  
Sam Stevens / EP-1 011979-037116

**WORK PERFORMED THIS QUARTER (Second - 2005):**

1. Submitted the first quarter 2005 *Quarterly Site Status Report* to the LADPW.

**WORK PROPOSED FOR THE NEXT QUARTER (Third - 2005):**

1. Submit Quarterly Site Status Report.

Current Phase of Project: Assessment/Closure  
Depth to Groundwater: 200+ feet Measured      Estimated X  
Groundwater Gradient: Unknown (Magnitude) Unknown (Direction)


**ATTACHMENTS:** Site Location Map (Figure 1)  
Site Map (Figure 2)

**DISCUSSION:**


The hydrocarbon-impacted soil at the site has been sufficiently assessed vertically and horizontally. Therefore, on behalf of Atlantic Richfield Company, Delta requests that no further actions be required of Atlantic Richfield Company for this site.

If you have any questions or comments concerning this correspondence, please contact Amy Mora at (949) 360-5789.

**DELTA ENVIRONMENTAL CONSULTANTS, INC.**

  
\_\_\_\_\_  
Amy Mora  
Project Manager

7/14/05  
\_\_\_\_\_  
Date



GENERAL NOTES:  
 BASE MAP FROM 3-D TOPO QUADS  
 MT. WILSON, CA. QUADRANGLE  
 7.5 MINUTE TOPOGRAPHIC MAP  
 1966  
 PHOTOREVISED 1988




FIGURE 1

SITE LOCATION MAP  
 ARCO FACILITY NO. 1592  
 5 W. FOOTHILL BOULEVARD  
 ARCADIA, CA.

PROJECT NO.  
 AM03-169

DRAWN BY

FILE NO.  
 A3-808-03


PREPARED BY  
 A. BAIRD

DATE  
 09 DEC 03

REV.  
 0

REVIEWED BY





### LEGEND

- B-1 ● SOIL VAPOR EXTRACTION WELL LOCATION
- B-2 • SOIL BORING LOCATION
- TSA ▼ TANK SOIL SAMPLE LOCATION
- D4A ▼ DISPENSER SOIL SAMPLE LOCATION
- ▨ APPROXIMATE LIMIT OF OVEREXCAVATION




FIGURE 2  
SITE MAP  
ARCO FACILITY NO. 1592  
5 WEST FOOTHILL BOULEVARD  
ARCADIA, CA.

PROJECT NO.  
AM03-169

FILE NO.  
A3-169-01

DATE  
17 MAR 04

DRAWN BY  
K. MARTIN

PREPARED BY  
A. BAIRD

REVIEWED BY

